


MICROFLUIDIC MOLDING



INVERT MOLD,
SEAL TO SURFACE.
PERFUSE PLGA SOLUTION
BY APPLYING
NEGATIVE PRESSURE.



BAKE MOLD + PLGA



PEEL PDMS FROM SURFACE





FIG. 3

SPIN COATING



APPLY PLGA SOLUTION TO PDMS MOLD, SPIN AT 2000 RPM.



BAKE MOLD + PLGA



PEEL SCAFFOLD FROM MOLD





FIG. 4





BEST AVAILABLE COPY

## FIGURE 6

A

В





## FIGURE 7

